

WK SERIES

2-wire TRANSMITTER



Monitors or signal converters are unnecessary.

Electric current output makes long wiring possible.

Direct connection to control instruments.

The ideal system for monitoring small compressor vibrations.

Sales SHINKAWA Electric Co., Ltd.

3rd Fl. Shin-kojimachi Bldg.3-3 Kojimachi 4-chome, Chiyoda-ku, Tokyo 102-0083, Japan Tel:+81-3-3263-4417 Fax:+81-3-3262-2171 E-mail: InternationalSalesEU@shinkawa.co.jp Web: https://www.shinkawa.co.jp/eng/

Manufacturing SHINKAWA Sensor Technology, Inc.

4-22 Yoshikawa-kogyodanchi, Higashihiroshima, Hiroshima 739-0153, Japan Tel: +81-82-429-1118 Fax: +81-82-429-0804 E-mail: info@sst.shinkawa.co.jp Web: https://www.shinkawa.co.jp/sst/

Please contact our service representatives for further information.

Published in Feb.2023

^{*} Specifications, outline drawings and other written information can be changed without notice.

^{*} When exporting Shinkawa products, permission may be required for export or service transactions, pursuant to the provision of the Foreign Exchange and Foreign Trade Act.

When re-exporting Shinkawa products, permission may be required from the US Department of Commerce, pursuant to the provision of the Export Administration Regulation (EAR).


SIMPLE WIRING - 2-WIRE TRANSMITTER

The WK series transmitter is an eddy-current type transmitter that incorporates vibration converter features, supplying the power and transmitting the signal with a 2-wire current loop. The WK system reduces equipment and wiring costs. Two kinds of transmitters are available - the WK-142K for shaft vibration, and the WK-142T for thrust position.


Monitors or vibration converters are unnecessary. Electric current output makes long wiring possible. Direct connection to control instruments.

 $\label{thm:compressorvibrations} \textbf{The ideal system for monitoring small compressor vibrations}.$

Example of SYSTEM CONFIGURATION



Outline Drawing



Specifications

		WK-142K	WK-142T		
ent Output	4 to 20mA Output Range	0 to 100 μm pk-pk, 0 to 125 μm pk-pk, 0 to 200 μm pk-pk, 0 to 250 μm pk-pk, 0 to 400 μm pk-pk	-0.6 to 0 to +0.6 mm, -0.635 to 0 to +0.635 mm (-25 mils to 0 to +25 mils)		
Current	4 to 20mA Output Conversion Accuracy	\pm 1.5% of full scale range (from test signal input pin to current output)	±1.0% of full scale range (from test signal input pin to current output		
	Max. Load Resistance	43.5×(Vps-12)Ω(Vps=Power supply voltage)			
	Calibration Material	JIS SCM440 flat (AISI 4140 equivalent)			
Output	Linear Range*	1.4 mm (Gap : 0.3 to 1.7 mm)			
õ	Scable Factor*	7.87 mV/µm			
Θαр	Scale Factor Error*	7.87mV/µm±6.5% typ. (including interchangeability errors) Step: 200µm, Target: 30 mm dia.			
	Output Impedance*	10 k Ω (it is calibrated load impedance at 10 M Ω)			
	Frequency Response*	5 Hz to 6,000 Hz (+0 dB, -3 dB) at 900 μm Gap			
System	Operating Temperature Range	Transmitter : 0 to 70°C Sensor & Extension cable : -34 to +177°C (Connector : Max.125°C			
Sys	Relative Humidity	95% RH (non-condensing)			
	Power Supply Voltage	12 to 35 VDC			
	System Cable Length	5 m. 7 m or 9 m	5 m, 7 m		


CE compliance

Model Code

For Shaft Vibration


oration			WK-142K /NB /DNC					
	Syst	em Cable Length		Output Range		Non-incendive	With DIN Mounting Clips	
ſ	1	5 m	1	0 to 100 µm pk-pk	1	CSA: Class I Div.2 Gr. A,B,C,D ATEX: Ex nA II T4 Gc		
Γ	2	7 m	2	0 to 125 µm pk-pk	8	KTL : Ex nA II T4		
	5	9 m	3	0 to 200 µm pk-pk	С	TR-CU: 2Ex nAIIT4 Gc X		
			4	0 to 250 µm pk-pk				
			5	0 to 400 µm pk-pk				

For Thrust Position




Outline Drawing and Model Code

WL Sensor



WW Extension Cable



••••

1

0000